Docket No. 50-245

2000

July 24, 1981

100

DISTRIBUTION:
Docket
ORB #5 RF
Subject File

MEMORANDUM FOR: E. L. Jordan, Deputy Director

Division of Resident and Regional

Reactor Inspection, IE

FROM:

Gus C. Lainas, Assistant Director

for Safety Assessment Division of Licensing

SUBJECT:

MILLSTONE 1 - ESF RESET CONTROL DESIGN DEFICIENC/ -

I&E BULLETIN 80-06

Task Interface Agreement ROI-80-15 assigned the responsibility to the Office of Nuclear Reactor Regulation for reviewing the licensee's responses to Items 1 and 3 of I&E Bulletin 80-06. Our review of Northeast Nuclear Energy Company responses to the bulletin for the Millstone Unit No. 1 are complete. The Technical Evaluation Report (TER) prepared by our contractor EG&G and our Safety Evaluation Report (SER) are enclosed.

We have concluded that the licensee has satisfied the concerns of I&E Bulletin 80-06 having completed modifications to four iso-condenser valves that could have moved from the "EMERGENCY" mdde upon ESF reset in accordance with the marked up drawings of the proposed modifications that NNECO provided to EG&G/SRO. Please confirm that the valves were modified and tested as scheduled prior to returning th power following the 1980-1981 extended refueling outage.

Original Signed By: G. C. Lainas

Gus C. Lainas, Assistant Director for Safety Assessment Division of Licensing

Enclosures: As stated

cc w/enclosures:

S. Minor

D. Crutchfield

H. Smith

J. Shea

8108070022 810724 PDR ADOCK 05000245 Q PDR

C/ORB#5:DL

OFFICE ORB#5:DL
URNAME JShea:dn )

NRC FORM 1-8 (10/80) IRCM 6240

ORB#5: DE HSmith 7/23/81 DCrutchfield

GCLainas 7/2381

OFFICIAL RECORD COPY

\* USGPO 1980-329-824