



LER 1-80-57 SUPPLEMENT ATTACHMENT

Facility: BSEP Unit No. 1

Event Date: 7-3-80

Following this event, the frequency of performing PT 6.2.1 was reduced from once per eighteen months to once per six months to ensure proper calibration. Based on the increased calibration frequency and the results of the past inspection, no further action is required on this event.