

LER #: 50-321/1981-073
Licensee: Georgia Power Company
Facility Name: Edwin I. Hatch
Docket #: 50-321

Narrative Report
for LER 50-321/1981-073

During normal power operation it was discovered that torus water temperature was 97⁰F. This exceeds the limit of less than or equal to 95⁰F. as stated in Tech. Specs. 3.7.A.1.c.

Torus cooling was immediately initiated and torus water temperature was decreased to less than 95⁰F. in less than 24 hours.

The cause of the torus water high temperature was due to continuous hot weather, thus increasing the temperature of the Rx building environment. This is a recurring problem during the hot months of the summer.