

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 F L S L S 1 2 0 0 1 0 0 0 0 0 0 3 4 1 1 1 1 4 5

LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 27 CAT 28

CON'T

01 L 6 0 5 0 0 0 3 3 5 7 0 7 0 5 8 1 3 0 8 0 3 8 1 9

REPORT SOURCE 29 30 DOCKET NUMBER 38 39 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During full power operation the MD containment pressure transmitter

03 alarmed intermittently several times and finally failed. Action was

04 taken in accordance with Tech Spec 3.3.2.1 and 3.3.1.1 and channel MD

05 (RPS and ESFAS) was placed in bypass. The transmitter was repaired and

06 channel MD was returned to service. There have been two previous LER's

07 of this nature 81-21 and 81-36.

08

09

SYSTEM CODE S D 11 CAUSE CODE E 12 CAUSE SUBCODE E 13 COMPONENT CODE I N S T R 14 COMP. SUBCODE T 15 VALVE SUBCODE Z 16

LER/RO REPORT NUMBER 17 EVENT YEAR 81 SEQUENTIAL REPORT NO. 037 OCCURRENCE CODE 03 REPORT TYPE L REVISION NO. 0

ACTION TAKEN A 18 FUTURE ACTION Z 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0000 ATTACHMENT SUBMITTED N 22 NRC FORM 368 N 23 PRIME CORP. SUPPLIER N 24 COMPONENT MANUFACTURER F1120 25

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 The transmitter was repaired by replacing the oscillator and the force

11 motor. The cause of the component failure is not known.

12

13

14

FACILITY STATUS E 26 % POWER 100 27 OTHER STATUS NA 28 METHOD OF DISCOVERY A 29 DISCOVERY DESCRIPTION Operator Observation 30

ACTIVITY CONTENT Z 31 RELEASED OF RELEASE Z 32 AMOUNT OF ACTIVITY NA 33 LOCATION OF RELEASE NA 34

PERSONNEL EXPOSURES NUMBER 000 35 TYPE Z 36 DESCRIPTION NA 37

PERSONNEL INJURIES NUMBER 000 38 DESCRIPTION NA 39

LOSS OF OR DAMAGE TO FACILITY TYPE Z 40 DESCRIPTION NA 41

PUBLICITY N 42 DESCRIPTION NA 43

NAME OF PREPARER P. L. Pace PHONE (305) 552-3654