



D. C. COOK UNIT TWO  
DOCKET NO. 50-316  
SUPPLEMENT TO LER NO. 81-032/03L-0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

TO GUARD AGAINST A FAILURE OF THE CHECK VALVES IN QUESTION. RFC NUMBER IS  
12-1861.