50.55(e) Report

Docket Nos. 50-361/362

TELEPHONE (213) 572-1695

N

12-

## Southern California Edison Company

P O BOX 800 2244 WALNUT GROVE AVENUE ROSEMEAD CALIFORNIA 91770

J. M. Curran

August 17, 1981

Mr. R. H. Engelken, Director Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission Region V Suite 202, Walnut Creek Plaza 1990 North California Boulevard Walnut Creek, California 94506

Dear Mr. Engelken:

Subject: Docket Nos. 50-361 and 50-362 San Onofre Nuclear Generating Station, Units 2 and 3

This letter confirms verbal notification on August 17, 1981 of a condition discovered in construction which is considered potentially reportable in accordance with 10CFR50.55(e). The guide lug inserts (shims) for reactor internals exhibit cracks which are detectable by visual examination. The condition has been confirmed by dye penetrant examination.

We are performing an evaluation of this condition and will submit an appropriate report in accordance with 10CFR50.55(e)(3) if the condition is determined to be reportable. If you have any questions or require additional information, please let me know.

Very truly yours,

J. M. Comon

cc: R. J. Pate (NRC, San Onofre Units 2 and 3) Dr. L. T. Papay



IE27 51/0

8109030115 810817 PDR ADOCK 05000361 S PDR