

## LICENSEE EVENT REPORT

**EXHIBIT A**

CONTROL BLOCK: [ ] [ ] [ ] [ ] [ ] [ ] (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

3	1	N	I	C	M	G	S	1	2	0	0	-	0	0	0	0	0	0	0	1	0	3	4	1	1	1	1	4	1	5						
7	6	9	LICENSEE CODE	14	15	LICENSE NUMBER										25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45

60

REPORT SOURCE L 0 5 0 0 0 3 6 9 7 0 1 8 0 9 8 1 8 0 1 9 0 3 8 1 3

**EVENT DESCRIPTION AND PROBABLE CONSEQUENCES**

3 2 | While in Mode 3, alarms were received at the HVAC panel in the Control Room  
3 3 | indicating a loss of sample flow through a radiation monitor (EMF-43A) for the  
3 4 | Control Room outside air intake. The monitor was declared inoperable per T.S.  
3 5 | 3.3.3.1 which is reportable pursuant to T.S. 6.9.1.13(b). Because of the  
3 6 | availability of a redundant "B" train, in addition to respiratory protective  
3 7 | equipment provided to Control Room personnel, this incident did not affect the  
3 8 | safe operation of the plant or the health and safety of the public.

SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE						COMP SUBCODE		VALVE SUBCODE		
3   9	7   8	B   1	B   1	(1)	X   1	(12)	Z   1	(13)	I   N   S   T   R   U	(14)	E   1	(15)	Z   1	(15)		
		9   10			11		12		13		14		15		16	
(17) LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.				OCCURRENCE CODE		REPORT TYPE				REVISION		
21	22	8   1		23	24	25	26	27	10   13	3	3	28	29	30	31	32
ACTION TAKEN AT UN		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		FROM FORMS		PRIME COMP SUPPLIER		COMPONENT MANUFACTURER		
33	34	Z   19	Z   20	Z   21	Z   22	35	36	37	38	N   1	N   2	N   3	L   4	G   0	6   3	47

**CAUSE DESCRIPTION AND CORRECTIVE ACTIONS**

The cause of this incident is unknown. Action statement #27 of Table 3.3-6 was implemented when the monitor was declared inoperable. Examination of the monitor revealed the vacuum pump was in the "auto" mode but had stopped. When it was switched to "manual" mode the pump started. The flow rate, vacuum and alarm setpoints were checked and found to be properly working. The pump was restarted in the "auto" mode and the alarm cleared.

in the 'auto' mode and the alarm cleared.

ACTIVITY CONTENT  
RELEASED OR RELEASED N/A AMOUNT OF ACTIVITY (35)  
1 6 Z (3) Z (34) N/A N/A LOCATION OF RELEASE (35)

PERSONNEL EXPOSURES  
NUMBER TYPE DESCRIPTION (3)  
1 7 10 10 (37) Z (38) N/A

7 8 9 10 11 12 13 14  
PERSONNEL INJURIES  
NUMBER DESCRIPTION 41  

1	2
---	---

 10/10/41 N/A

1 8 9 10 11 12 N/A 30  
LOSS OF OR DAMAGE TO FACILITY (43)  
TYPE DESCRIPTION

1 3 42 N/A  
7 8 9 10  
**PUBLICITY**  
RECORDED - DESCRIPTION (45) **NBC USE ONLY**

2 0 N/A

**NAME OF PREPARED**

Phillip B. Nardoci

(704) 373-7432