LICENSEE EVENT REPORT

	. LICENSEE EVENT REPORT
	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	N C B E P 2 2 0 0 - 10 0 0 0 - 10 0 3 4 1 1 1 1 4 57 CAT 58 5
CON'T 0 1 7 8	REPORT L 6 0 5 0 - 0 3 2 4 7 0 8 2 5 8 1 8 0 9 1 1 8 1 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 During plant operation with no evolutions in progress, the RCIC System automatically
0 3	isolated due to the receipt of a spurious RCIC isolation logic bus "A" signal that
0 4	resulted in the closure of the RCIC turbine steam supply inboard isolation valve,
0 5	2-E51-F007. At the time of this event, the HPCI System was operable. This event did
0 6	not affect the health and safety of the public.
0 7	
0 8	Technical Specifications 3.7-4, 6.9.1.9b
7 8	SYSTEM CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCOD
1 0	The cause of this event is presently unknown. Checks of the RCIC System isolation
	logic circuitry and instrumentation did not reveal any problems. The RCIC System was
7 2	then declared operable and returned to service. Following a determination the cause
1 3	of this event, a supplement to this report will be submitted.
7 8	PACILITY STATUS SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 NA A 31 Operational event
1 6	ACTIVITY CONTENT AMOUNT OF ACTIVITY (35) I C C C C C C C C C C C C C C C C C C
1 7	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 NA 9 PERSONNEL INJURIES 13 80
1 8	NA DESCRIPTION (41) O O O O O O O O O O O O O O O O O O O
1 9	TYPE DESCRIPTION NA NA 80
2 0 7 8	PUBLICITY ISSUED DESCRIPTION (45) 9 10 STORE ADDCK 05000324 PDR ADDCK 05000324 PDR (919) 457-9521
	NAME OF PREPARER PHONE

LER ATTACHMENT - RO # 2-81-83

Facility: BSEP Unit No. 2 Event Date: 3/25/81

During the investigation of this event, it was discovered that RCIC System steam line area ambient temperature switch, 2-F51-TS-N603A was inoperable. The inoperability of this switch is being reported in LER 2-81-73.