LICENSEE EVENT REPORT

	LICENSEE EVENT REPORT
	CONTROL BLOCK
0 1	N J S G S 1 2 0 0 - 0 0 0 0 - 0 0
0 1 , 8	- MEPORT L 6 0 5 0 0 0 2 7 2 7 0 9 0 2 8 1 8 0 9 1 4 8 1 9 60 EVENT DATE 74 75 REPORT DATE 80
0 2	On September 2, 1981, during a routine containment inspection, an operator discovered
0 3	service water leaking from a secondary coil on No. 14 containment fan coil unit
0 4	(CFCU), at a rate of approximately 1 gallon per minute. In accordance with
0 5	NRC IE Bulletin 80-24, the NRC was notified of the service water leak in containment
0 6	by telephone, with written confirmation transmitted within the next 24 hours. No. 14)
0 7	CFCU was removed from service, and declared inoperable. Action statement 3.6.2.3.a
0 8	was entered at 1935 hours, September 2, 1981.
0 9	SYSTEN CAUSE CODE SUBCODE COMPONENT CODE SUBCODE SUBCO
	LER RO EVENT YEAR SEDURNTAL SECURITIES NOT TYPE NO
1 0	The leakage was due to secondary coil failure. The leaking cooling coil was blank
11	I flanged off and the CFCU was tested satisfactory and returned to service. Action
1 2	statement 3.6.2.3.a was terminated at 1930 hours, September 3, 1981.
1 3	(81-10, 81-11, 81-31, 81-39, 81-64, 81-72, 81-74, 81-77)
14	
7 8	SCACILITY STATUS A POWER OTHER STATUS OTH
1 7 8	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 O O O 37 Z 38 N/A PERSONNEL INJURIES 13 80
1 8	NUMBER DESCRIPTION (41) N/A
1 9	LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION N/A
	PUBLICITY SSUED DESCRIPTION (5) NRC USE ONLY
7 8	N/A
DR A	20610 810914 ARER Frank Dickey PHONE: 609-935-5100