TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401 400 Chestnut Street Tower II

September 21, 1981

Mr. James P. O'Reilly, Director Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Region II - Suite 3100 101 Marietta Street Atlanta, Georgia 30303

Dear Mr. O'Reilly:

PHIPPS BEND NUCLEAR PLANT - REPORTABLE DEFICIENCY - INADEQUATE WELDS ON EMBEDDED PIPE SLEEVES TO PLATES (NCR PBNP-160 AND AUDIT PB-G-80-14 DEFICIENCY NO. 2)

Initial notification of the subject deficiency was made to NRC-OIE, Region II, Inspector R. W. Wright on October 24, 1980. The first, second, and third interim reports were submitted on November 24, 1980 and February 20, and May 15, 1981, respectively. In compliance with paragraph 50.55(e) of 10 CFR Part 50, this letter constitutes the fourth interim report on the subject deficiency. TVA is still in the progress of evaluating the subject deficiency. This interim report is being filed because deferral of Phipps Bend construction activities has not allowed any significant progress to be made on this problem. TVA anticipates transmitting the final report on or before July 2, 1982. If you have any questions regarding this subject, please call Jim Domer at FTS 857-2014.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

Nuclear Regulation and Safety

cc: Mr. Victor Siello, Director Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Washington, DC 20555

109290609 8109 ADOCK 050005