

SEP 22 1981



Lutheran Medical Center
ATTN: Thomas Murray
Vice President
2609 Franklin Blvd.
Cleveland, OH 44113

License No. 34-01869-01
License No. 34-01869-02

Gentlemen:

This refers to the routine safety inspection conducted by Mr. R. E. Burgin of this office on September 2, 1981, of activities authorized by NRC Byproduct Material Licenses No. 34-01869-01 and No. 34-01869-02 and to the discussion of our findings with you and members of your staff at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

During this inspection, certain of your activities appeared to be in noncompliance with NRC requirements, as specified in enclosed Appendix A. A written response, submitted under oath or affirmation, is required.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

D. J. Sreniawski, Chief
Materials Radiation Protection
Section 2

Enclosure: Appendix A,
Notice of Violation

cc w/encl:
DMB/Document Control Desk (RLOS)

RIII
Burgin/jp
9/17/81

EIII
Sreniawski
9/18/81

IE07
s
//

8109290636 810922
NMS LIC30
34-01869-01 PDR