

DUKE POWER COMPANY

POWER BUILDING

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR.  
VICE PRESIDENT  
STEAM PRODUCTION

September 24, 1981

TELEPHONE: AREA 704  
373-4083


Mr. J. P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Region II  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Re: McGuire Nuclear Station Unit 1  
Docket No. 50-369

Dear Mr. O'Reilly:

In the LER's of Reportable Occurrence Report #'s RO-369/81-120, 81-121, and 81-124, item #13 (Cause Subcode) was incorrectly given as "E" (Instrument). The entries should have been "B" (Mechanical), "A" (Electrical), and "X" (Other), respectively. Attached are revision 1 of the LER's to these three Reportable Occurrence Reports reflecting these changes. The originally submitted attachments to the LER's do not contain these errors and thus are still applicable. We regret any confusion or inconvenience this may have caused.

Very truly yours,

  
William O. Parker, Jr.

PBN/smh

Attachments

cc: Director  
Office of Management and Program Analysis  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Mr. Bill Lavalley  
Nuclear Safety Analysis Center  
Post Office Box 10412  
Palo Alto, California 94303

Ms. M. J. Graham  
Resident Inspector-NRC  
McGuire Nuclear Station



IE22  
S  
1/1

8110070332 810924  
PDR ADOCK 05000369  
S PDR