LICENSEE EVENT REPORT

	LICENSEE EVENT REPORT
	CONTROL BLOCK
0 1	N J S G S 1 2 0 0 - 0 0 0 0 - 0 0 0 4 1 1 1 1 1 4 5 E
0 1 7 8	AEPORT LE 0 5 0 0 0 2 7 2 7 0 9 2 9 8 1 8 1 0 2 1 8 1 0 5 0 0 0 0 2 7 2 7 0 9 2 9 8 1 8 1 0 2 1 8 1 0
0 2	On two separate occasions, September 29, 1981 and October 1, 1981, an operator
0 3	noticed that the Channel 3 Pressurizer Level was reading higher than the other two
0 4	channels. At 0720 and 0835 hours, respectively, the channel was declared inoperable,
0 5	l and limiting condition for operation (LCO) 3.3.1.1, Action 7 was entered.
0 6	
0 7	
0 8	
0 9 7 8	SYSTEN CAUSE CODE SUBCODE COMPONENT CODE SUBCODE SUBCO
	LER RO EVENT YEAR REPORT NO CODE TYPE NO
	ACTION FUTURE COMPONENT SHUTDOWN HOURS 22 ATTACHMENT FORM SUB- SUPPLIER MANUFACTURE MANUFA
	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
10	On both occasions the Channel 3 Pressuricer Level bistable was placed in the tripped
11	Condition within one hour. On September 29 the transmitter was recalibrated, tested
1 2	satisfactorily, and returned to service. On October 1 the transmitter was backfilled
13	1 to remove trapped air, recalibrated, tested satisfactorily, and returned to service.
14	L At 1815 hours, September 30, 1981 and 2210 hours, October 3, 1981, respectively,
1 5	P LCO 3.3.1.1 Action 7 was terminated. (81-42) FACILITY POWER OTHER STATUS 30 DISCOVERY DESCRIPTION 32 E 28 0 9 7 29 N/A A 31 Operator Observation
	CTIVITY CONTENT 12 13 AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36 N/A N/A
7 8	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 O O O 37 Z 38 N/A
7 8	PERSONNEL INJURIES NUMBER DESCRIPTION (41)
1 R	0 0 0 0 N/A
1 9	TYPE DESCRIPTION 43
	PUBLICITY SSUED DESCRIPTION (5) B111030403 B11021 PDR ADDCK 05000272 PDR ADDCK 05000272 PDR ADDCK 05000272
7 8	N/A S
	NAME OF PREPARER Frank Dickey PHONE: 609-935-5100