

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | FLS | L | S | 2 | 000-000000-000 | 41111 | 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

CON'T
01 | REPORT SOURCE | L | 05000389 | 053183 | 063083 | 9
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
02 | While in Mode 3 during initial startup, an operator transiting the
03 | personnel air lock noticed the inner equalizing valve did not shut. The
04 | equalizing valve was shut manually and maintained closed while repairs
05 | were made. This was the second event of this type. The health and safety
06 | of the public were not adversely affected.
07 |
08 |

09 | SYSTEM CODE | S | A | 11 | CAUSE CODE | E | 12 | CAUSE SUBCODE | B | 13 | COMPONENT CODE | V | A | L | V | E | X | 14 | COMP SUBCODE | A | 15 | VALVE SUBCODE | L | 16 |
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40
17 | LER/RO REPORT NUMBER | 8 | 3 | 22 | SEQUENTIAL REPORT NO. | 0 | 1 | 1 | 8 | 26 | OCCURRENCE CODE | 0 | 1 | 3 | 29 | REPORT TYPE | L | 30 | REVISION NO. | 0 | 32 |
18 | ACTION TAKEN | A | 18 | FUTURE ACTION | Z | 19 | EFFECT ON PLANT | Z | 20 | SHUTDOWN METHOD | Z | 21 | HOURS | 0 | 0 | 0 | 0 | 22 | ATTACHMENT SUBMITTED | N | 23 | NPRO-4 FORM SUB | N | 24 | PRIME COMP SUPPLIER | A | 25 | COMPONENT MANUFACTURER | C | 3 | 1 | 0 | 25 |
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
10 | Upon inspection, the operating linkage for the equalizing valve was found
11 | to be broken. Further investigation showed that the valve movement was
12 | severely restricted. The valve was replaced, the linkage repaired and the
13 | air lock declared operable.
14 |

15 | FACILITY STATUS | B | 28 | % POWER | 0 | 0 | 0 | 29 | OTHER STATUS | 30 | METHOD OF DISCOVERY | A | 31 | DISCOVERY DESCRIPTION | Operator Observation | 32 |
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

16 | ACTIVITY CONTENT | Z | 33 | RELEASED OF RELEASE | Z | 34 | ACTIVITY | 35 | LOCATION OF RELEASE | NA | 36 |
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50


17 | PERSONNEL EXPOSURE NUMBER | 0 | 0 | 0 | 37 | TYPE | 38 | DESCRIPTION | NA | 39 |
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

18 | PERSONNEL INJURIES NUMBER | 0 | 0 | 0 | 40 | DESCRIPTION | NA | 41 | *terr*
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

19 | LOSS OF OR DAMAGE TO FACILITY TYPE | Z | 42 | DESCRIPTION | NA | 43 |
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

20 | PUBLICITY ISSUED DESCRIPTION | NA | 45 | NRC USE ONLY
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

NAME OF PREPARER G. E. Walling PHONE (305)465-3550x3364



June 30, 1983
PNS-LI-83-461-1

Mr. James P. O'Reilly
Regional Administrator, Region II
U. S. Nuclear Regulatory Commission
101 Marietta Street N.W., Suite 2900
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 389-83-18

ST. LUCIE UNIT 2

DATE OF OCCURRENCE: MAY 31, 1983

PERSONNEL AIR LOCK

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide 30-day notification of the subject occurrence.

Very truly yours,

K. Williams
J. W. Williams, Jr.
Vice President
Nuclear Energy

JWW/PLP/js

Attachment

cc: Director, Office of Inspection and Enforcement (30)
Harold F. Reis, Esquire
File 933.1 SL

OFFICIAL COPY

1022

11

PEOPLE...SERVING PEOPLE