



ATTACHMENT TO LER 83-044  
SOUTHERN CALIFORNIA EDISON COMPANY  
SAN ONOFRE NUCLEAR GENERATING STATION  
UNIT NO. 3, DOCKET NO. 50-362

SUPPLEMENTAL INFORMATION FOR CAUSE DESCRIPTION AND CORRECTIVE ACTION:

As corrective action, the two licensed control room operators involved were disciplined for failure to follow established administrative controls for abnormal valve lineups and positioning of locked valves. Other operations personnel who were involved with shift reliefs during this 19-hour period have been warned about failure to properly identify the abnormal position of this containment isolation valve. Also, each station operating crew has been briefed in detail on the importance of verbatim compliance with Station procedures and administrative controls which exist to preclude incidents of this nature.

In addition, commencement of an upgrading of both classroom and on-the-job training in administrative controls, will be implemented. Items such as compliance with procedures, abnormal valve alignments, control of containment valves, and Control Room command structure will be addressed to increase the effectiveness of administrative controls.

Administrative controls are under evaluation for locked valves in non-safety-related systems, such as service air, which include valves that perform a safety-related function (e.g., containment isolation). If the need for procedure revision is identified as a result of this evaluation, these revisions will be made.

Lastly, a revision of the Technical Specifications to permit intermittent opening of MU-055 under administrative control is currently being developed. These actions are considered adequate to prevent recurrence of this event.

rm  
**Southern California Edison Company**

SAN ONOFRE NUCLEAR GENERATING STATION  
P.O. BOX 128  
SAN CLEMENTE, CALIFORNIA 92672

6  
RECEIVED  
NRC

1983 AUG -1 PM 12:39  
SCE

REGIDIV

TELEPHONE  
(714) 492-7700

H. B. RAY  
STATION MANAGER

July 27, 1983

U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region V  
1450 Maria Lane, Suite 210  
Walnut Creek, California 94596-5368

Attention: Mr. J. B. Martin, Regional Administrator

Dear Sir:

Subject: Docket No. 50-362  
14-Day Follow-Up Report  
Licensee Event Report No. 83-044  
San Onofre Nuclear Generating Station, Unit 3


Reference: Letter, H.B. Ray (SCE) to J.B. Martin (NRC),  
dated July 13, 1983

The referenced letter provided you with confirmation of our prompt notification, pursuant to Section 6.9.1.12.b of Appendix A, Technical Specifications to Facility Operating License NPP-15 for San Onofre Unit 3, of a reportable occurrence involving the Containment Isolation System.

Pursuant to Section 6.9.1.12.b, this submittal provides the required 14-day follow-up report and a copy of Licensee Event Report (LER) No. 83-044 to address this event.

If there are any questions regarding this event, please contact me.

Sincerely,



Enclosure: LER 83-044

IE-22

Mr. J.B. Martin

-2-

cc: A.E. Chaffee (USNRC Resident Inspector, Units 2 and 3)  
J.P. Stewart (USNRC Resident Inspector, Units 2 and 3)

U.S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement

U.S. Nuclear Regulatory Commission  
Division of Technical Information and Document Control

Institute of Nuclear Power Operations (INPO)