Regulatory File Cy.




## NORTHERN STATES POWER COMPANY

January 5, 1973

Docket No. 50-263

Mr A Giambusso, Deputy Director for Reactor Projects Directorate of Licensing U S Atomic Energy Commission Washington, DC 20545



338

Dear Mr Glambusso:

MONTICELLO NUCLEAR GENERATING PLANT E-5979 Postulated Fipe Failures Outside Containment

Your letter of December 18 requested documentation and analysis of the consequences of postulated pipe failures outside of the containment structure, including the rupture of a main steam or feedwater line. Attached to your letter was a list of information that you will require, where applicable, for our Monticello facility. If the results of our analysis indicate the need for plant modifications, you have requested a description of such modifications and a schedule estimate for implementing the proposed changes.

Based on investigations to date, we do not see that the postulated type failures will interfere with safe shutdown of the reactor. The following describes the original design general approach taken regarding failures of high energy process lines external to primary containment:

Reactor building pipe tunnel area - This area was analyzed for the largest possible pipe break, a main steam line break, for possible damage to Class I structural members. As a result a protective panel was provided to allow relief of the pressure into the turbine building. No equipment located in the tunnel which is required to function to mitigate the consequences of the break would be adversely affected by the atmosphere within the tunnel following the break.

Suppression pool area - Analysis of a rupture of the largest high pressure line, the HPCI steam line, showed no damage to the structure or containment that would interfere with safe plant shutdown. Further the equipment items required to mitigate the consequences of this accident are not located in the affected area.

9102120651 730105 PDR ADOCK 05000260 PDR

## NORTH TATES POWER COMMANY

- 2 -

Reactor building, ground floor and above - This area was analyzed for failure of the only system normally containing high pressure, high temperature fluid, the reactor water cleanup system. As a result, the design accommodates the pressure transient resulting from a pipe failure so that no structural damage will occur to interfere with safe plant shutdown. The equipment items required to mitigate the consequences of this accident would not be prevented from performing their functions as a result of the accident.

Turbine building - This area was investigated from the standpoint of gross structural failure as a result of a main steam line break and safe shutdown of the plant is assured.

As we previously indicated to you, no significant problems have been identified whereby failure of steam or feedwater lines would prevent a plant shutdown. However we are proceeding with the detailed investigation in accordance with the informational requirements attached to your letter of December 18, 1972 and our reporting will be submitted by June 15, 1973.

Yours very truly,

EtWar

E C Ward, Director Engineering Vice Presidential Staff

Co: G Charnoff D E Nelson

AEC DISTINUT	TION FOR PART (TEMPORAR		T MATTE	CONTROL NO: 328
				10.00 V MI
FROM	DATE OF DOC:	DATE P	EC'D LL	TILE- TR   MEMO   RPT   OTHEN
Northern States Power Company Minneapolis, Minn. 55401		1-12-7		x
E. C. Ward TO:	1-5-73 ORIG	Contraction of the second s	THER	SENT AEC PDA X
				SENT LOCAL PDR X
Mr. Giambusso CLASS: (U) PROP INFO	1 INPUT	NO CYS N	2010	DOCKET NO:
Christian Control Into	3111.01	10 010 1		100001 1101
DESCRIPTION:		1 ENCLOSUR	·	50-263
Ltr re our 12-18-72 ltrfurni regarding postulated pipe failure containment structure	s outside	1	ACKNO!	Remove
PLANT NORES: TOBUCCEIC	FOR ACTION/1	NFORMATIO	N 1-	15=73 AB
W/ Copies W/ Copies CLARK(L) STOLZ(L) W/ Copies W/ Copies GOLLER(L) VASSALLO(L) W/ Copies W/ Copies KNIEL(L) H. DENTON W/ Copies W/ Copies	W/4 C CHITW W/C DICKE	Copies COD(FM) Copies	W/ W/ W/	Copies UNGBLOOD(E) Copies GAN(E) Copies Copies
and the second states of the second	LITERNAL	DISTRIBU	FION	
REG FILETECH REVIEWAEC FDRHEIMDRIEOGC, ROOM P-506ASCHROEDERMUNTZING/STAFFMACCARYCASELANGE(2)GIAMBUSSOPAWLICKIBOYD-L(EWR)SHAODEYOUNG-L(PWR)KNUTHSKOVHOLT-LSTELLOP. COLLINSMOOREHOUSTONHOUSTONREG OFRLONGFILE & RECION (2)LONGMORRISBENAROYA	VOLLMER DENTON GRIMES GAMMILL KASTNER BALLARD SPANGLER ENVIRO MULLER DICKER KNIGHTON YOUNGBLOO PROJ LEAD	D ER	HARLESS F & M SMILEY NUSSBAUME LIC ASST. SERVICE MASON WILSON MAIGRET SMITH GEARIN DIGGS TEETS LEE	A/T IND
	EXTERNAL DIS	TRIBUTION		
1-LOCAL FDR <u>Minneapolis, Minn</u> . 1-DTIE(ABERNATRY) 1-NSIC(BUCHANAN) 1-ASLB-YORE/SAYRE WOODWARD/H. ST. 6-CYS ACRS HOLDING				BROOKHAVEN NAT. LAB 1-AGMED (WALTER KOESTER,

the second s

and the latter of the same of the same of