

APPENDIX A

NOTICE OF VIOLATION

Georgia Power Company
Vogtle 1 and 2

Docket Nos. 50-424 & 50-425
License Nos. CPPR-108 & CPPR-109

As a result of the inspection conducted on May 24-28, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified.

10 CFR 50, Appendix B, Criterion XVI and the accepted QA Program (PSAR Section 17.1.16) require that measures be established to assure that conditions adverse to quality such as nonconformances are promptly corrected. Procedure GD-T-09 requires that all equipment at its permanent location shall be made access-controlled to the greatest practical degree. Bechtel document X61H02-85-2, paragraph 2b-4, Storing Pump on Foundation, also requires sealing protective covers.

Contrary to the above, conditions adverse to quality were not promptly corrected. During April 1981, the licensee identified in a QA audit that controls were inadequate to maintain the protective cover integrity for the chemical and volume control system (CVCS) charging pump (2-1208-P6-006). Another QA audit in January 1982 identified that similar in-place storage maintenance controls appeared inadequate. Prompt corrective action was not taken in that the inspector found the condition still existed for this and four other CVCS charging pumps.

This is a Severity Level IV Violation (Supplement II).

Pursuant to the provisions of 10 CFR 2.201, you are hereby required to submit to this office within thirty days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violation; (2) the reasons for the violation if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

Date: July 12, 1982