## LICENSEE EVENT REPORT

LICENSEE EVENT REPORT
CONTROL BLOCK: [ ] [ ] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 N C B E P 2 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5 5  LICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58
CON'T  O 1  SOURCE L 6 0 5 0 - 0 3 2 4 7 0 8 0 4 8 2 8 0 8 3 1 8 2 9  EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10  While manually opening the suppression pool suction supply valve to B pump of B loop
RHR, 2-E11-F004B, the valve stem spun freely beyond the full open valve position. The
0 4 unit was in cold shutdown at the time of this discovery. This event did not affect the
[0]5] [health and safety of the public.
0 6
0 7 {
Technical Specifications 3.5.3.2, 6.9.1.9b
7 8 9  SYSTEM CAUSE CODE SUBCODE  CODE SUBCODE  COMPONENT CODE SUBCODE  COMPONENT CODE SUBCODE  SUBCODE  TO B  10 11 12 12 13 13 13 18 18 19 19 16
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)   COCCURRENCE   REPORT   TYPE   NO.   NO.
1 0 Disassembly of the valve revealed a complete fracture of the stem approximate 6 inches
from the valve gate. A new valve stem was installed and the valve was satisfactorily
cycled and returned to service. Following the completion of a metallurgical analysis
of the failed valve stem a supplement will be submitted outlining any required further
corrective actions regarding this event.
7 8 9 FACILITY STATUS SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32  1 5 G 28 0 0 0 29 NA A 31 Operator Surveillance
7 8 9 10 12 13 44 45 46 80 AMOUNT OF ACTIVITY (35) NA
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) NA NA
7 8 9 PERSONNEL INJURIES NUMBER DESCRIPTION (41)  NUMBER DESCRIPTION (41)  NA
7 8 9 11 12 80 LOSS OF OR DAMAGE TO FACILITY (43)
TYPE DESCRIPTION  1 9 Z 42 NA  8209160603 820831  7 8 9 10 8209160603 820831
ISSUED DESCRIPTION S PDR
7 8 9 10 68 69 80 5 NAME OF RESARRED M. J. Pastva, Jr. PHONE 919-457-9521