LICENSEE EVENT REPORT

_	LICENSEE EVENT REPORT
	CONTROL BLOCK: [] [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
7 8	N J S G S 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 5 CAT 58
0 1 7 8	SOURCE L 6 0 5 0 0 0 2 7 2 7 0 8 2 5 8 2 8 0 9 1 6 8 2 9 EVENT DATE 74 75 REPORT DATE 80
0 2	EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) At 1920 hours, August 25, 1982, it was discovered that the 100' Elevation Contain-
0 3	ment Air Lock outer door was not sealing properly. The air lock was declared
0 4	inoperable and Action Statement 3.6.1.3 was entered at 1920 hours.
0 5	
0 6	
0 7	
08	9
0 9	SYSTEM CAUSE CODE SUBCODE SUBC
	LER RO EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE REPORT TYPE NO. O 6 6 6 1 0 3 L L 0 0
	ACTION CUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT SUBMITTED FORM SUB. PRIME COMP. COMPONENT MANUFACTURER SUBMITTED FORM SUB. SUPPLIER SUBMITTED FORM SUB. SUPPLIER SUPPLIER SUBMITTED FORM SUB. SUPPLIER MANUFACTURER LC 1 3 0 26 47 CAUSE DESCRIFT. ON AND CORRECTIVE ACTIONS (27)
1 0	The seal was damaged by personnel closing the door with excessive force. The seal
11	was replaced and the door tested satisfactorily. The air lock was declared
1 2	operable and Action Statement 3.6.1.3 was terminated at 2215 hours, August 25, 1982.
1 3	Training is being performed in proper operation of air lock doors. Design Change
1 4 8	Packages have been submitted to install snubbers on air lock doors.
1 5 7 8	STATUS SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 E 28 0 9 9 29 N/A B 31 Suzveillance Testing
	CTIVITY CONTENT ELEASED OF RELEASE AMOUNT OF ACTIVITY 35 Z 33 Z 34 N/A N/A LOCATION OF RELEASE 36 N/A
1 7	NUMBER TYPE DESCRIPTION 39 N/A
18	NUMBER DESCRIPTION 41 N/A
1 9	9 11 12 LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION N/A
2 0	9 PUBLICITY 8209300201 B20916 NRC USE ONLY 80 PDR ADOCK 05000272 N/A S PDR
8	9 10 68 69 80 5 NAME OF PREPARER R. Heller PHONE 609/935-6000 Ext 3078