

## LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
---	---

REPORT SOURCE

L	6	0	5	0	0	0	2	0	6	7	0	9	1	9	8	2	8	1	0	1	9	8	2	9
---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---	---

DOCKET NUMBER

EVENT DATE

REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 While in Mode 5, the Fire Water Crosstie was damaged during new construction activities.

03 The Unit 1 West Fire Water Pump was already out of service for maintenance. With the

04 loss of the Crosstie, Unit 1 was serviced by a single Fire Water Pump. Compliance

05 with Technical Specifications was achieved with the return to service of the West Fire

06 Water Pump on September 22, 1982. There was no effect on public health and safety as

07 a result of this incident.

08		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80			
0		9		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80	
0		9		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80	
0		9		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70		71		72		73		74		75		76		77		78		79		80	
0		9		7		8		9		10		11		12		13		14		15		16		17		18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47		48		49		50		51		52		53		54		55		56		57		58		59		60		61		62		63		64		65		66		67		68		69		70																					

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The Crosstie was damaged in the process of digging for new construction. Corrective

1 1 actions included the return to service of the West Fire Water Pump, and rigging of

1 2 back-up fire suppression hoses.

1	3											80		
1	4											80		
FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION				80		
1	5	G	28	0	0	0	29	NA	30	A	31	Observed by personnel	32	80
ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE						80		
1	6	Z	33	Z	34	NA	35	NA	36				80	
PERSONNEL EXPOSURES		TYPE		DESCRIPTION								80		
1	7	0	0	0	37	Z	38	NA	39				80	
PERSONNEL INJURIES		DESCRIPTION										80		
1	8	0	0	0	40	NA	41						80	
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION								80		
1	9	Z	42	NA	43								80	
PUBLICITY		ISSUED		DESCRIPTION								80		
2	0	N	44											80
		8210280068		821019		PDR		ADOCK		05000206		S		80
						PDR								80
												NRC USE ONLY	80	

NAME OF PREPARED

8210280068 821019  
PDR ADCK 05000206  
S PDR

H. B. Ray

Telephone: 714/492-7700

NRC USE ONLY