

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 1 1 1 1 1 1 1 (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1	F	L	S	L	I	L	I	L	1	2	0	0	1	0	0	1	0	1	0	1	0	1	3	4	1	1	1	1	4	0	1	1	5
7	3																																

0 1	L	I	S	L	I	L	I	L	1	2	0	0	1	0	0	1	0	1	0	1	0	1	3	4	1	1	1	1	4	0	1	1	5
7	3	LICENSE CODE	14	15	LICENSE NUMBER	25	26	LICENSE TYPE	30	CAT 58																							

CON'T

0 1	R	E	P	O	T	S	O	S	U	R	5	0	1	5	0	0	0	3	3	5	7	0	1	9	2	3	8	2	3	1	0	2	5	8	2	5
7	3	REPORT SOURCE	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80			

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 While operating at approximately 100% power, the T hot input to the sub-cooled margin monitor became erratic giving false indication and alarms, thus rendering the system inoperable. The subcooled margin monitor was restored to operable status within one half hour, well within the time limit of action required by TS 3.3.3.8. There was no adverse effect on the health or safety of the public. This is the second event of this type.

0 3 (Reference 335-82-22).

0 9	SYSTEM CODE	1	1	p	11	x	12	z	13	z	z	z	z	z	z	z	z	z	z	z	z	z	z	z	z	z	z	z	z	z	z	z	z	z						
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	
17	LERIRO REPORT NUMBER	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56
ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS	ATTACHMENT SUBMITTED	NPD-4 FORMS SUB.	PRIME COMP SUPPLIER	COMPONENT MANUFACTURER	REVISION NO.																															
x	z	z	z	0	0	0	z	z	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0					

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 No cause was determined for this event. The I&C spec investigator reported that the malfunction cleared when he removed the cover of the junction box enclosing the T hot transmitter which provides input to the SCMM. The condition could not be repeated and has not happened again.

1 4	FACILITY STATUS	% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION	30
1 5	F	1	0	1	Operator Observation	31
7	8	9	10	11		32
ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY				33
1 6	z	z	z	z	NA	34
7	8	9	10	11	NA	44
PERSONNEL EXPOSURES	NUMBER	TYPE	DESCRIPTION			35
1 7	0	0	0	z	NA	36
7	8	9	10	11	NA	44
PERSONNEL INJURIES	NUMBER	DESCRIPTION				37
1 8	0	0	0	0	NA	38
7	8	9	10	11	NA	44
LOSS OF OR DAMAGE TO FACILITY	TYPE	DESCRIPTION				39
1 9	Z	z	z	z	NA	40
7	8	9	10	11	NA	44
PUBLICITY ISSUED	DESCRIPTION					41
2 0	N	z	z	z	NA	42
7	8	9	10	11	NA	44

NRC USE ONLY

NAME OF PREPARER P. K. Green PHONE (305) 552-3676

8211040090 821025
PDR ADDOCK 05000335
S PDR