LICENSEE EVENT REPORT

	:
	CONTROL BLOCK: PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION
7 3	M I D C C 2 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 6 TOTAL SE TOMBER STATE OF THE STATE OF TH
0 1 7 3	SOURCE L 6 0 5 0 0 0 3 1 6 7 1 1 2 8 8 2 8 1 2 8 8 2 9
0 2	WHILE IN OPERATIONAL MODE 5, A SECURITY GUARD NOTICED THE TEMPORARY FIRE SEAL FOR
0 3	FIRE BARRIER PENETRATION W-9392 MISSING AND THE SEAL FOR PEN. W-9393 NON-FUNCTIONAL.
0 4	THE PENETRATIONS ARE IN WALLS BETWEEN THE TURBINE BLDG. AND THE EMERG. DIESEL GENER-
0 5	ATOR ROOMS. THE CONDITION WAS NONCONSERVATIVE WITH RESPECT TO T.S. 3.7.10. THE
0 6	ACTION REQUIREMENTS WERE MET. THE SEALS WERE AGAIN FOUND TO BE NON-FUNCTIONAL ON
0 7	TWO OCCASIONS, 11/30/82 AND 12/2/82. THE SEALS WERE REPAIRED. FIRST OCCURRENCE OF
0 3	THIS TYPE.
0 9	SYSTEM CAUSE CODE SUBCODE SUBC
	LER RO EVENT YEAR SEQUENTIAL REPORT NO. CODE TYPE NO.
	ACTION FUTURE COMPONENT SUBMITTED FORM SUB. SUPPLIER ZOMPONENT MANUFACTURER ZOMPONENT ZOMPON
110	THE TEMPORARY FIRE SEALS APPEARED TO HAVE BEEN INTENTIONALLY VIOLATED ON ALL 3
11	OCCASIONS. PLANT SECURITY ESTABLISHED A SURVEILLANCE ON THE FIRE SEALS BUT DID NOT
1 2	CATCH ANYBODY TAMPERING WITH THEM. DISCIPLINARY ACTION WOULD HAVE BEEN TAKEN IF THE
1 3	PERSON RESPONSIBLE FOR VIOLATING THESE SEALS HAD BEEN CAUGHT.
7 8	
1 5	ACILITY STATUS 30 NA STATUS 30 NETHOD OF DISCOVERY DESCRIPTION 32 NA SECURITY GUARD OBSERVATION
1 6	LEASED OF RELEASE NA AMOUNT OF ACTIVITY 35
1 7	O O O O O O O O NA
1 8	NA NA NA NA
1 9	Z 42 NA SPDR ADDCK 05000316
2 0	NRC USE ONLY N (46) NA
	NAME OF PREPARER DAVID G. WIZNER