LICENSEE EVENT REPORT NI ROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) 0 1 CON'T 0 1 6 0 5 0 0 0 3 3 6 7 1 2 1 0 8 2 8 0 1 0 5 8 3 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) During routine steady state power operation, power was lost to the 120 volt A.C. Vital | Bus #VIAC-3. The plant was operated in accordance with Technical Specification State-0 3 ment 3.8.2.1 for fifty minutes. Similar LERS: None 0 5 0 6 0 7 CAUSE COMP CODE CODE COMPONENT CODE 0 OCCURRENCE REVISION SEQUENTIAL REPORT CODE TYPE NO. 0 14 18 REPORT 0 3 L 01 NPRD-4 FORM SUB ATTACHMENT PRIME COMP COMPONENT HOURS (22) N 23 Z (21) 0 0 0 LA (25) X (18) CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) With VIAC-3 being powered by the alternate supply and the normal supply tagged out for 1 0 maintenance, a worker accidently bumped the static switch causing the supply to be 1 1 switched from the alternate supply to the normal supply. Covers have been installed 1 2 to prevent recurrence. 1 3 METHOD OF OTHER STATUS (30) & POWER 0 0 (29) NA NA Z (31 ACTIVITY CONTENT AMOUNT OF ACTIVITY (35) NA PERSONNEL EXPOSURES DESCRIPTION (39) NA PERSONNEL INJURIES DESCRIPTION (41) NUMBER 0 0 (40) NA 8301140063 830105 PDR ADOCK 05000336 OSS OF OR DAMAGE TO FACILITY (43) DESCRIPTION NA 10 PUBLICITY NRC USE ONLY DESCRIPTION (45 NA 447-1791 Ext. 4725 Gary E. Komosky NAME OF PREPARER