## LICENSEE EVENT REPORT

	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	M I D C C 2 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 57 CAT 58
0 1 7 8	SOURCE 60 0 5 0 0 0 3 1 6 0 68 69 EVENT DATE 74 75 REPORT DATE 80
0 2	L DURING AN ECCS FLOW BALANCE TEST, A FLOW RATE OF 300 GPM COULD NOT BE OBTAINED
0 3	THROUGH TRAIN "B" OF THE SAFETY INJECTION SYSTEM. INVESTIGATION REVEALED THAT,
0 4	IN ADDITION TO THE NORMAL VALVE INTERNALS, A SECOND VALVE DISC WAS LODGED IN THE
0 5	OUTLET OF 4 INCH CHECK VALVE, SI-152S. THE UNATTACHED VALVE DISC HAD BEEN LEFT
0 6	LIN THE VALVE DURING A PREVIOUS REPAIR IN OCTOBER 1981. (RO-81-050/01T-0). THE
0 7	OBSTRUCTION WAS REMOVED AND THE FLOW BALANCE TEST WAS COMPLETED SATISFACTORILY.
0 B	80
0 9	SYSTEM CODE CODE SUBCODE SUBCO
	17 REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 32
	ACTION FUTURE COMPONENT METHOD HOURS 22 ATTACHMENT NPRD-4 PRIME COMP SUPPLIER MANUFACTURER    D   18   Z   19   Z   20   Z   21   0   0   0   0   N   23   N   24   N   25   V   0   8   5   26
	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  I THIS IS AN INTERRIM REPORT PENDING COMPLETION OF THE INVESTIGATION.
1 0	THIS IS AN INTERRIM REPORT PENDING COMPLETION OF THE INVESTIGATION.
1 1	
1 2	
1 3	
1 4	80
	PACILITY STATUS  N POWER  OTHER STATUS  OTHE
	CTIVITY CONTENT ELEASED OF RELEASE AMOUNT OF ACTIVITY 35  Z 33 Z 34 N/A  N/A
7 8	9 10 11 44 45  PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)  10 10   (37)   Z   (38)   N/A
1 8	9 11 12 13  PERSONNEL INJURIES  NUMBER DESCRIPTION (41)
1 8	0 0 0 0 0 N/A
1 9	TYPE DESCRIPTION PDR ADDCK 05000316 PDR S PDR
20	PUBLICITY ISSUED DESCRIPTION 45  NAC USE ONLY  NAC USE ONLY  RESULT OF THE PROPERTY OF THE PRO
	NAME OF PREPARER DAVID G. WIZNER PHONE 616-465-5901