LICENSEE EVENT REPORT

	LICENSEL EAFINI HELOHI
*	CONTROL BLOCK (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 7 B	N E C P R 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 5 CAT 58
CON'T	PREPORT 1 6 0 5 0 0 0 2 9 8 7 1 2 2 1 8 2 8 0 1 2 0 8 3 9 EVENT DATE 74 75 REPORT DATE 80 VENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 2	During normal operation, while performing S.P. 6.2.2.1.4, pressure switch RHR-PS-120A
0 3	(RHR pump "A" discharge pressure) setpoint was found outside the range specified in
0 4	Table 3.2.B on Tech. Specs. There were no other abnormal occurrences and a redundant
0 5	pressure switch was operable. This occurrence presented no adverse consequences from
0 6	the standpoint of public health and safety.
0 7	
7 8	80
0 9	SYSTEM CAUSE CAUSE SUBCODE COMPONENT CODE SUBCODE SUSCESSORIA SUSCODE SUBCODE SUBCODE SUSCODE SUSCODE SUSCODE SUSCODE
	SEQUENTIAL REPORT NO. 17) REPORT 8 2
10	The pressure switch (Static-O-Ring Model 5N-AA3-X) was adjusted to the required set-
111	point and retested. However, subsequent testing showed a nonrepeatable trip point and
1 2	the pressure switch was replaced. The apparent cause of the setpoint instability was
1 3	diaphragm failure. The failure rate of this type of switch will be monitored and
1 4	further action taken if and when appropriate.
15	E 28 0 9 9 29 NA B 31 Operator Observation
	TIVITY CONTENT EASED OF RELEASE AMOUNT OF ACTIVITY (35) Z (33) Z (34) NA
1 7 8	NUMBER TYPE DESCRIPTION (39) 0 10 0 37 Z 38 NA PERSONNEL INJURIES NA 80
	NUMBER DESCRIPTION (41) 0 0 0 0 NA
1 2	USS OF OH DAMAGE TO FACILIT (13) Z (42) NA
, н	B301310124 B30120 PDR ADDCK 05000298 S PDR NRC USE ONLY
	N OF NA S PDR
	NAME OF PREPARES R. W. Krause PHONE 402-825-3811