




GULF STATES UTILITIES COMPANY

POST OFFICE BOX 2951 BEAUMONT, TEXAS 77704

AREA CODE 713 838-6631

January 28, 1983
RBG - 14,232
File Nos. G9.5, G9.25.1.1

Mr. John T. Collins, Regional Administrator
U. S. Nuclear Regulatory Commission
Region IV, Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, TX 76011



Dear Mr. Collins:

River Bend Station Unit 1
Docket No. 50-458
Interim Report/DR-74

On August 30, 1982, Gulf States Utilities Company (GSU) notified the Nuclear Regulatory Commission's Region IV Office of a condition potentially reportable under 10CFR50.55(e) concerning the incorrect installation of 1/2-inch drilled-in-expansion-type anchor bolts used to seismically support emergency lighting battery units in the River Bend Station control room (DR-74). GSU has not completed its evaluation at this time. An interim or final status report will be provided by March 28, 1983.

Sincerely,

William J. Booker
J. E. Booker
Manager-Engineering,
Nuclear Fuels & Licensing
River Bend Nuclear Group

^{PJD}
JEB/PJD/do

cc: Director of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

R. L. Brown (SRI)

IE 27

8302070458 830128
PDR ADOCK 05000458
S PDR