

TELECOPY TO NRC
June 17, 1981

OFFICIAL COPY

U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, NW
Suite 3100
Atlanta, Georgia 30303



296
NRC-30-260/8130

Reported under Technical Specification 6.7.2.A (5)

Date of Occurrence: 6/16/81 Time of Occurrence: 0830 hrs. Unit 3

Technical Specification Involved: Table 3.1.A

Conditions Prior to Occurrence

Unit 1 in refueling outage; unit 2 in preparation for restart from cold shutdown; and unit 3 in normal operation at 1,073 MWe.

Identification and Description of Occurrence

During routine surveillance testing (Surveillance Instruction 4.1.A.14) turbine first-stage permissive switches PB-1-81A and B, and PB-1-91A and B were found above technical specification limits. The greatest out of tolerance was 11.9 percent.

Apparent Cause of Occurrence

Setpoint drift.

Other Related Events

<u>NRC-30-259</u>	<u>NRC-30-260</u>	<u>NRC-30-296</u>
7816	7802	7907
7908	7917	7912
8058	7924	7918
8129	8023	8022
8132	8057	8030
	8123	8045
	8128	8052
		8107

REGIONAL DIRECTOR
DEPUTY DIRECTOR
ASSISTANT TO DIRECTOR
DIRECTOR, RRPI
DIRECTOR, EPOS
DIRECTOR, ENF/INV
DIRECTOR, ETI
PUBLIC AFFAIRS OFFICER

Corrective Action Taken or Planned

Setpoints were reset to a more conservative value, and the surveillance instruction completed satisfactorily. Additionally, a design change request (DCR 1398) has been initiated to replace these switches with an analog transmitter with a trip switch.

J.A. [Signature]
L. L. Abercrombie
Power Plant Superintendent
Brunswick Nuclear Plant
B108250365 B10617
PDR ADOCK 05000296
S PDR

IE-22
1/0