## LICENSEE EVENT REPORT

LICENSEE EVENT NEI ONT
CONTROL BLOCK LITTE TO THE PRINT OR TY ALL REQUIRED INFORMATION
0 1 N J S G S 1 2 0 0 - 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
CON'T SOURCE LEG 0 5 0 0 0 2 7 2 7 0 7 2 0 8 1 8 0 8 1 9 8 1
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  O 2 On July 20, 1981, while attempting to place the No. 15 CFCU in service the control
o [3]   room operator noticed that there was no service water flow at high speed and
insufficient flow at low speed. The CFCU was delared inoperable and action statement
0   5   3.6.2.3.a was entered at 1811 hours, July 20, 1981.
OIE L SCOMP VALVE
SYSTEM CAUSE CODE SUBCODE SUBC
TO REPORT B 1 22 23 24 26 27 28 29 30 31 30 COMPOLENT
TAKEN ACTION ON PLANT METHOD HOURS (22) SUBMITTED FORM SUB SUPPLIES OF 1 2 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  [1] [2]   Equipment failure. The high pressure side of flow transmitter FA-3543Z-1 was plugged
solid with silt. Flow transmitter FA-3543Z-1 sensing line was blown clear and the
[1]2   transmitter was recalibrated satisfactorily. The No. 15 CFCU was tested satisfactory
and returned to service. Action statement 3.6.2.3.a was terminated at 0050 hours,
[1]4   on July 21, 1981. (80-23)
7 8 9 FACILITY STATUS STATUS OTHER STATUS ON METHOD OF DISCOVERY DESCRIPTION 32 DISCOVERY DESCRIPTION 32  A 30 Operator noticed service water flow.
7 8 9 10 12 13  ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35  N/A  11 6 2 3 2 34 N/A  80
7 8 9 10 11 44 45 PERSONNEL EXPOSURES (39)
1 7 0 0 0 3 Z 3E N/A
PERSONNEL INJURIES NUMBER DESCRIPTION 41  [1 8 0 0 0 40 N/A 80
TYPE DESCRIPTION 43
1 9 Z 42 N/A  NRC USE ONLY
PUBLICITY ISSUED DESCRIPTION 45  N/A  68 69 80
8108310326 810819 J. Varga PHONE: 609-935-5100
PDR ADOCK 05000272 ARER PDR