LICENSEE EVENT REPORT
CONTROL BLOCK
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE JO 57 CAT 50
CON'T REPORT LIGHT SOURCE LIGHT SOURCE LIGHT SOURCE LIGHT SOURCE LIGHT SOURCE
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) On five separate occasions on July 23, July 24, and July 25, 1981, No. 22 CSD
breaker ripped from an unidentified cause. There were no indicating flags showing
o on the relays. No. 21 CSD breaker was closed manually. Action statement 3.8.2.1.a
[7]5 was entered at 1614 and 1803 hours, July 23, 1211 and 1805 hours, July 24, and
0 [6] [1624 ! Dars, July 25, 1981.
0 E L
SYSTEM CODE SUBCODE COMPONENT CODE SUBCODE SUB
LER RO EVENT YEAR SEQUENTIAL OCCURRENCE REPORT TYPE N: N: N: N: N: N: N: N
TAKEN ACTION ON PLANT METHOD HOURS 22 SUBMITTED FORM SUB SUPPLIER MANUFACTURES MANU
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (2) The cause of the breaker trips is still undetermined. It is being investigated.
The immediate action in each of the five occurrences was to manually close the
No. 21 CSD breaker. At 1624 and 1805 hours, July 23, 1222 and 1813 hours, July 24,
terminated. The status of discovery description of the status of the st
RELEASED OF RELEASE AMOUNT OF ACTIVITY 35
NUMBER TYPE DESCRIPTION (35) O O O O O SE DESCRIPTION (35) PERSONNEL INJURIES 13
1 8 d ol d (1) NA
LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION 1 9 Z (42) NA
PUBLICITY ISSUED DESCRIPTION 45
2 10 NA 68 69 80 5
8109010508 810821 Frank Dickey PHONE 609-935-5100 2 PDR ADDCK 05030311 PDR