LICENSEE EVENT REPORT

11.	LICENSEE EVENT REPORT
	CONTROL BLOCK: [] [] [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 8	M I D C C I D O O O O O O O O O O O O O O O O O O
O 1 7 8	SOURCE LIG 0 5 0 0 3 1 5 7 0 8 1 1 8 1 8 0 9 1 0 8 1 9 9 1
0 2	DURING SURVEILLANCE TESTING OF THE AB EMERGENCY DIESEL GENERATOR, THE FUEL OIL SUPPLY
0 3	IN THE DAY TANK WAS INADVERTENTLY ALLOWED TO BE COMPLETELY DEPLETED. THIS CAUSED THE
0 4	ENGINE TO TRIP. IT WAS SUBSEQUENTLY DECLARED INOPERABLE BECAUSE AIR HAD ENTERED THE
0 5	FUEL LINES CAUSING TWO IMMEDIATE RESTART ATTEMPTS TO FAIL. THE APPRORIATE ACTION OF
0 6	T.S. 3.8.1.1 WAS MET. THIS WAS THE FIRST OCCURRENCE OF THIS TYPE AND NO PROBABLE
0 7	CONSEQUENCES RESULTED.
0 8	80
7 8	SYSTEM CAUSE CAUSE SUBCODE SUB
	TO REPORT NUMBER 21 22 23 24 26 27 25 29 30 31 32
	ACTION FUTURE EFFECT SHUTDOWN METHOD HOURS 22 ATTACHMENT NPRD-4 FORM SUB. PRIME COMPONENT MANUFACTURER SUBMITTED FORM SUB. PRIME COMPONENT MANUFACTURER SUBMITTED FORM SUB. PRIME COMPONENT MANUFACTURER Z3 34 45 47 47 47
	THE SURVEILLANCE PROCEDURE 1-OHP 4030.STP.027 WAS DEFICIENT IN THAT IT RELIED ON THE
10	THE CONTRACTOR THOUSAND TO THE CONTRACTOR TO THE
	TOTE WHOM TO MODE IT DE QUETTOE OF EVENTS IN THE STATE OF
1 2	LEAD TO A CONDITION WHERE THE ACTUAL LEVEL IN THE TANK WAS NOT CORRECTLY REPRESENTED
1 3	BY THE LEVEL ALARMS. A CHANGE HAS BEEN WRITTEN TO CORRECT THE PROCEDURE DEFICIENCY.
7 8	9
1 5	FACILITY STATUS SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 OPERATOR OBSERVATION BO
	ACTIVITY CONTENT DELEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA LOCATION OF RELEASE 36
1 7	PERSONNEL EXPOSURES NUMBER 0 0 0 0 337 Z 38 DESCRIPTION 39 NA
To be	PERSONNEL INJURIES NUMBER DESCRIPTION 41) NA
2 8	9 11 12 LOSS OF OR DAMAGE TO EARLY IV (43)
1 9	Z 42 NA
20	PUBLICITY (45) PDR ADDCK 05000315 PDR PDR ADDCK 05000315
7 8	NAME OF PREPARER D. M. DRAPER PHONE: (616) 465-5901 X 1490