

DONALD C. COOK NUCLEAR PLANT P.O. Box 458, Bridgman, Michigan 49106 (616) 465-5901

August 18, 1981

Mr. J.G. Keppler, Regional Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137



Operating License DPR-58 and DPR-74 Docket No. 50-315 and 50-316

Dear Mr. Keppler:

This is to confirm my telephone report utilizing the red phone at 1530 hours on August 17, 1981, and subsequent notification to your Region III Inspector, Mr. E. Swanson. The purpose of this call was to advise the Nuclear Regulatory Commission that a seismic inadequacy existed in addition to that reported on August 14, 1981, concerning the structural anchorage for certain pieces of equipment comprising the Unit 1 and 2 Electrical Power Systems.

A followup report will be submitted by August 30, 1981.

Sincerely,

D.V. Shaller Plant Manager

/bab

cc: J.E. Dolan

R.S. Hunter R.W. Jurgensen

R.F. Kroeger

K.J. Vehstedt

E. Swanson/N. DuBry RO:III

R.C. Callen MPSC

G. Charnoff, Esq.

J.M. Hennigan W. Lavallee EPRI

PNSRC

J.F. Stietzei

E.L. Townley

Dir., IE (40 copies)

nin MIPC (4 copies)

IEO/