

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CONT

0	1
B	

REPORT SOURCE

1	6	0	5	0	0	0	3	2	7	7	0	9	1	1	8	1	8	1	0	8	8	1	9
60	61	DOCKET NUMBER					68	69	EVENT DATE					74	75	REPORT DATE					80		

EVENT DESCRIPTION AND PROBABLE CONSEQUENCE (10)

19	SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE								
8	M	B	11	X	17	Z	13	I	N	S	T	R	U	14	E	15	Z	16			
	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26			
17	EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.												
LER/RO REPORT NUMBER	8	1	21	22	1	1	7	24	25	26	27	0	3	28	29	L	30	31	0	32	
ACTION TAKEN	FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD 4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURE						
E	18	X	19	Z	20	Z	21	0	0	0	0	22	N	23	N	24	L	25	B	2	0
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (21)

0 | The oxygen analyzer zero adjustment control had been inadvertently moved causing the
1 | analyzer to indicate excessive amounts of oxygen. The zero adjustment control was
2 | reset and the analyzer recalibrated and functionally tested. A Maintenance Request
3 | has been initiated to secure a protective box around the zero adjustment control to
4 | prevent any future accidental movement.

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION		
5	E	28	1	0	0	29	NA	B	31	Operator observation
ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE				
6	Z	33	Z	34	NA	35	NA	36		
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION				
7	0	0	0	37	Z	38	NA	39		
PERSONNEL INJURIES		NUMBER		DESCRIPTION						
8	0	0	0	40		41	NA	42		
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION						
9	Z	42		43	NA	44		45		
PUBLICITY		ISSUED		DESCRIPTION						
10	N	44		45	NA	46		47		

8110150331 811008
PDR ADOCK 05000327
S PDR

NRC USE ONLY

8110150331 811008
PDR ADOCK 05000327
S PDR

NRC USE ONLY v

18