

Inryco, Inc.
Concrete Systems Division
Docket No. 99900731/81-01

NOTICE OF VIOLATION

As a result of the inspection conducted on July 13-17, 1981, and in accordance with the Interim Enforcement Policy, 45 FR 66754 (October 7, 1980), the following violation was identified:

Paragraph 21.6 of 10 CFR Part 21 states, in part, "Each individual partnership, corporation or other entity subject to the regulations in this part, shall post current copies of the following documents in a conspicuous position on any premises, within the United States where the activities subject to this part are conducted (1) the regulations in this part, (2) Section 206 of the Energy Reorganization Act of 1974, and (3) procedures adopted pursuant to the regulations in this part.

"If posting of the regulations in this part or the procedures adopted pursuant to the regulations in this part is not practicable . . . in addition to posting Section 206, post a notice which describes the regulations/procedures, including the name of the individual to whom reports may be made, and states where they may be examined."

Contrary to the above, Section 206 and the required procedures, or alternate notice, were not posted in the Inryco manufacturing facility.

This is a Severity Level VI violation (Supplement II).

8110230294 811006
PDR GA999 EMVINRY
99900731 PDR