L'CENSEE EVENT REPORT

	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	N C B Z P 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5 5 HICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58 5
0 1 7 8	REPORT L 6 0 5 0 - 0 3 2 5 7 0 9 2 5 8 1 8 1 0 1 6 8 1 9 SOURCE 60 BI DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
0 2	While running the HPCI System auxiliary oil pump in accordance with surveillance
0 3	requirements, it was discovered through local inspection of the pump that it was
0 4	uncoupled from its motor due to a broken pump - motor coupling. This event did not
0 5	affect the health and safety of the public.
0 6	
0 7	
08	Technical Specifications 3.5.1, 6.9.1.9b
0 9	SYSTEM CAUSE CAUSE SUBCODE SUB
	17) REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 32
	ACTION FUTURE TAKEN ACTION ON PLANT SHUTDOWN METHOD HOURS 22 ATTACHMENT SUBMITTED FORM SUB. PRIME COMP. SUPPLIER MANUFACTURER TO 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
10	Routine operation of the pump, Model No. L110 Chicago Lovejoys, since initial unit
111	startup allowed the coupling to become misaligned and fail at the time of the event.
1 2	The coupling was replaced, aligned, and the pump was tested for proper operation and
1 3	returned to service. A check of plant documentation showed this event is isolated;
14	therefore, no further corrective action is required or planned.
7 8	FACILITY STATUS OTHER STATUS OTHER STATUS DISCOVERY DISCOVERY DISCOVERY DESCRIPTION (32) [C (28) 0 1 8 (29) NA A A A A A A A A A A A A A A A A A A
	ACTIVITY CONTENT JELEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA LOCATION OF RELEASE 36 NA NA
7 8	9 10 11 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) NA NA
7 8	PERSONNEL INJURIES NUMBER DESCRIPTION (41) NA
7 8	9 11 12 LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION NA
7 8	9 8110290465 811016 NBC USE ONLY
20	ISSUED DESCRIPTION (45) PDR ADDCK 05000325 PDR NA
7 8	9 10 M. J. Pastva, Jr. (919)457-9521 PHONE: PHONE: 9