mr H. C. hance



PTP-QC-81-185 Turkey Point Plant October 22, 1981

TO:

Mr. J. P. O'Reilly, Director, Region II Office of Inspection and Elforcement U. S. Nuclear Regulatory Commission Atlanta, Gaorgia 30303

FROM:

Mr. J. K. Hays, Plant Manager - Maclear Turkey Point Plant - OPR 31 and 41 Florida Power and Light Company Miami, Florida

SUBJECT:

MEMO FOR FACSIMILE TRANSMISSION TO CONFIRM

REPORTABLE OCCURRENCE 251-81-11

This memo confirms our notification of the subject prompt notification reportable occurrence made Thursday, October 22, 1981, to Mr. H. C. Dance of your office as follows:

OCCURAENCE

On Wednesday evening, October 21, 1981, a routine periodic test performed during partial draining of the primary system at the beginning of a planned refueling outage revealed that the flow path associated with the buron injection tank was obstructed.

CORRECTIVE ACTION

The flow path was re-established by alternating pump operation and raising the thermostat settings for the related heat tracing. A flow path to the hot legs was verified to be operable by establishing flow and the unit was in cold shutdown condition.

lant Manager - Muclear

JKH:SF B: NRC-RO

REGIONAL DIRECTOR DEPUTY DIRECTOR ASSISTANT TO DIRECTOR DIRECTOR, RRPI DIRECTOR, ENF/INV DIRECTOR, ET! SHISLIC AFFAIRS OFFICER

8110290472 811022 PDR ADDCK 05000251