1

## LICENSEE EVENT REPORT

.

	EIGENSEE EVENT REPORT
,	CONTROL BLOCK: [ ] [] (PLEASE PRINT OR TYPE ALL REQUIRES INFORMATION)
0 1	N C B E P 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 5 EICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58
CON'T	REPORT L 6 0 5 0 - 0 3 2 5 7 0 1 1 8 8 1 0 0 2 1 2 8 1 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
0 2	During the performance of Control rod operability check, PT 14.1, rod 26-07 would not
0 3	select. A similar event involving rod selectability was reported in LER 2-80-90 on
0 4	November 19, 1980. This event did not affect the health or safety of the public.
0 5	
0 6	
0 7	
0 8	Technical Specifications 3.1.3.1, 6.9.1.9b
0 9	SYSTEM CAUSE CAUSE SUBCODE COMPONENT CODE SUBCODE SUBC
	17 REPORT NUMBER 21 22 23 24 26 27 26 29 30 31 32
	ACTION FUTURE ACTION ON PLANT SHUTDOW!. HOURS 22 ATTACHMENT SUBMITTED FORM SLIB. SUPPLIER MANUFACTURER    B   8   X   19   Z   20   Z   21   0   0   0   0   N   23   Y   24   N   25   X   9   9   9   9   9   9   9   9   9
	A loose solder joint in the rod select switch occurred as a result of the frequent use
11	of the switch. A new solder joint was made, and the rod was successfully selected.
1 2	An Engineering Work Request has been written to study the feasibility of replacing
1 3	these switches with others of a different design in order to extend their operational
1 4	lifetime.
7 8	FACILITY SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 NA B 31 Periodic Test
	ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) NA LOCATION OF RELEASE (36) NA N
1 7	PERSONNEL EXPOSURES NUMBER 1YPE DESCRIPTION 39 NA NA 80
1 8	PERSONNEL INJURIES NUMBER DESCRIPTION 41  0 0 0 40 NA
7 8	9 11 12 80 LOSS OF OR DAMAGE TO FACILITY (43)
1 9	1 Z (G)
1 8	PUBLICITY PDR ADOCK 05000325 PDR NRC USE ONLY
2 0	NA IIIIIIII
	NAME OF PREPARER M. J. Pastva, Jr. PHONE 919-457-9521