




ARKANSAS POWER & LIGHT COMPANY
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

September 11, 1981

ØCANØ981Ø5

Mr. K. V. Seyfrit, Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011



SUBJECT: Arkansas Nuclear One - Unit 1 & 2
Docket No. 50-313, 50-368
License No. DPR-51, NPF-6
Main Feedwater Turbine Overspeed
(File: 1510, 2-1510)

Gentlemen:

Your letter of August 11, 1981, requested information related to the possibility that the overspeed and subsequent destruction of the ANO-2 main feedwater turbine could render inoperable a safety related system. In our investigation of this occurrence we have found that no safety related systems were or could have been damaged or otherwise rendered inoperable by the failure of this turbine. The results of our investigation are now under review by our legal staff and we expect to be able to provide a summary of those results to you by October 1, 1981.

Very truly yours,

Donald A. Ruster
for David C. Trimble
Manager, Licensing

DCT: kb

B111060503 B111014
PDR ADDCK 05000368
S PDR

1501