LICENSEE EVENT REPORT

ICENSEE EVENT REPORT	
CONTROL BLOCK:	OR TYPE ALL REQUIRED INFORMATION)
M N P I N 1 2 0 0 - 0 0 0 0 - 0 0	
60 61 DOLKET NUMBER 68 60 60 500 500 500 500 500 500 500 500 5	18/1/8/1/0/2/7/8/1/9
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) With No. 122 Fire Pump out of service, the daily	MEPOHI DATE 80
Fire Pump was not done on September 27. Test do	one on subsequent to
that No. 121 Fire Pump was operable during the period. The most recent instance	
of a missed surveillance test was RO 81-05. Tec	sh Spac 4 16 B 2
effect on public health and safety.	on opec 4.10.8.2 applies. No
SYSTEM CAUSE CAUSE COMPONENT CODE A B 10 A 12 A 13 Z Z Z Z Z Z Z	COMP VALVE SUBCODE Z 14 Z (15) 7 (16)
TARES DESCRIPTION AND CORRECTIVE ACTIONS (27) Personnel error. The fact that No. 122 Fire Pump was inadvertently omitted on the control board.	TYPE TYPE
inadvertently omitted on the control board operators	shift turnover sheet. The
importance of complete and accurate shift turnover w will review this report.	as stressed. Involved personnel
ACTUITY STATUS POWER OTHER STATUS OTHER STATUS OTHER STATUS ACTUAL TO STATUS OTHER STATUS ACTUAL TO STATUS OTHER STATUS OTHER STATUS ACTUAL TO STATUS OTHER STATUS ACTUAL TO STATUS OTHER	DISCOVERY DESCRIPTION (32) tor Observation
AMOUNT OF ACTIVITY (35) NA NA	LOCATION OF HELEASE (16)
THE PRODUCE EXPOSURES A TYPE TYPE TYPE NA TYPE NA TYPE TO NO. 13 2 38 NA	80
O O O O NA	BO
DESCRIPTION OF THE PROPERTY (3)	80
B111060642 B11027 PDR ADDCK 05000282 PDR	NAC USE OUT Y
MANY OF PHENAMEN_ A. A. Hunstad	68 69 en 2 en