TENNESSEE VALLEY ANTHOREGYON ...

400 Chestnut Street Tower II

November 81, N981 4 A8: 5

Mr. James P. O'Reilly, Director Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Region II - Suite 3100 101 Marietta Street Atlanta, Georgia 30303

Dear Mr. O'Reilly:

50-518

HARTSVILLE AND PHIPPS BEND NUCLEAR PLANTS - REPORTABLE DEFICIENCY - RPS PANEL DESIGN DEFICIENCIES (NCR PRC 80-31)

Initial report of the subject deficiency was made to NRC-OIE, Region II Inspector, F. S. Cantrell, on August 7, 1980. The first, second, third, and fourth interim reports on the subject deficiency were transmitted on September 3, November 18, 1980, February 12, and April 24, 1981, respectively. In compliance with paragraph 50.55(e) of 10 CFR Part 50, this constitutes the fifth interim report for the subject deficiency.

Proposed corrective actions have been transmitted to TVA by General Electric. The review of these corrective actions is not complete at this time. We anticipate transmitting the final report on or before May 4, 1982. TVA considers 10 CFR Part 21 applicable to this reportable deficiency. If you have any questions concerning this subject, please call Jim Domer at FTS 858-2725.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager

Nuclear Regulation and Safety

cc: Mr. Victor Stello, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Washington, DC 20555

B111100659 811103 PDR ADDCK 05000518 TE22 OFFICIAL COPY