LICENSEE EVENT REPORT TED 01-20/21

	LER 81-28/3L
	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	V T V Y S 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 1 6 57 CAT 58
CON'T	SOURCE L 6 0 5 0 0 0 2 7 1 7 1 0 1 7 8 1 8 1 1 1 1 1 8 1 9
0 2	During routine shutdown operations, when B RRMG Set was shut down, the field breaker
0 3	failed to open. This effectively disabled the recirc pump trip instrumentation for
0 4	B RRMG Set. T. S. Section 3.2.1 requires this instrumentation to be operable during
0 5	power operation. There were no significant occurrences as a result of this event,
0 6	nor were there any adverse affects to public health or safety. A previous similar
0 7	loccurrence was reported as LER 81-10/3L.
0 8	
7 8 0 9 7 8	SYSTEM CAUSE CAUSE SUBCODE COMPONENT CODE SUBCODE SUBC
	17) REPORT 8 1
	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
10	The cause of the occurrence was binding in the operating mechanism of the breaker
	due to a partially seized bearing. A new breaker will be installed and tested
1 2	prior to startup. This breaker is a General Electric Model AK-25.
1 3	
114	9 80
1 5	FACILITY STATUS OTHER STATUS (30) METHOD OF DISCOVERY DESCRIPTION (32) D (28) O O O (29) NA A A (31) Bkr failed to func when RRMG shut down
	9 10 12 13 44 45 46 46 ACTIVITY CONTENT AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)
1 6	Z 33 Z 34 NA
1 7	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 0 0 0 (37) Z (38) NA
7 8	9 PERSONNEL INJURIES NUMBER DESCRIPTION (41)
1 8	NA NA
1 9	LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION NA
7 8	PUBLICITY ISSUED OESCRIPTION 45 NA S PDR ADDCK 05000271 S PDR DESCRIPTION 45
7 8	9 10 80 69 80 5 NAME OF SPEARS Warren P. Murphy PHONE (802) 257-7711