	LICENSEE EVENT REPORT
	CONTROL BLOCK:               (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 7 8	NY IP S 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 5 GAT 58
0 1 7 8	REPORT LG 0 5 0 0 0 0 2 4 7 7 1 0 0 9 8 1 8 1 1 1 1 3 6 1 9 9 8 1 8 69 EVENT DATE 75 REPORT DATE 80
0 2	While at cold shutdown Code Safety Valve MS 48A on No. 21 Main Steam
0 3	Line was inspected, to determine why the valve was lifting at a lower
0 4	than specified pressure. The inspection revealed defective parts in the
0 5	valve internals. There were no adverse consequences of this event as
0 6	the valve would have performed its required functions.
0 7	
0 8	80
0 9	SYSTEM CAUSE CAUSE SUBCODE COMPONENT CODE SUBCODE SUBC
	TREPORT   SEQUENTIAL REPORT NO.   OCCURRENCE CODE   REPORT TYPE   NO.
10	Internal inspection of the Crosby Safety Valve Type HA-65W size 6-R-10,
111	revealed a broken section on the disc holder. The defective parts
1 2	were replaced, the valve tested satisfactorly and returned to service.
1 3	
7 8	9 80
1 5	FACILITY STATUS SPOWER OTHER STATUS OF DISCOVERY DESCRIPTION (32)  G 28 0 0 0 0 29 N/A CTIVITY CONTENT  METHOD OF DISCOVERY DESCRIPTION (32)  OPERATOR OBSERVATION  44 45 46
7 8	ELEASED OF RELEASE AMOUNT OF ACTIVITY (35)    Z   (33)   Z   (34)   N/A    PERSONNEL EXPOSURES    N/A   LOCATION OF RELEASE (36)   N/A   80
7 8	0 0 0 0 0 0 Z 38 N/A  9 PERSONNEL INITIALIZATION 80
1 8	NUMBEH DESCRIPTION (41)  O O O O O O O O O O O O O O O O O O O
1 9	Z   (2)   N/A
2 0	ISSUED DESCRIPTION (45) S PDR
, 8	9 10 914-526-5181 °