

Portland General Electric Company Trojan Nuclear Plant 71760 Columbia River Hwy Rainier, Oregon 97048 (503) 556-3713

February 21, 1990 CPY-068-90

U.S. Nuclear Regulatory Commission Document Control Desk Washington DC 20555

## Gentlemen:

Licensee Event Report No. 89-07, Revision 2, is attached. This reports an event in which the allowable closure times for control room ventilation isolation dampers were exceeded during a test. Revision 1 submitted October 13, 1989 incorrectly reported that changes had been effected for a procedure. This error was due to a misunderstanding on the part of the compliance engineer and the Responsible Manager concerning the status of the change. This revision corrects the mis-statement and sets a completion date for the change. The compliance engineer has been admonished concerning his responsibilities for accuracies in LERs. The Responsible Manager has moved on to other duties. Administrative controls have been instituted in the LER generation process to avoid future occurrences of this nature.

Sincerely,

C. P. Yundt General Manager Trojan Nuclear Plant

Sundt

c: Mr. John B. Martin Regional Administrator, Region V US Nuclear Regulatory Commission

> Mr. David Stewart-Smith State of Oregon Department of Energy

Mr. R. C. Barr USNRC Resident Inspector Trojan Nuclear Plant

1527