

UNITED STATES

NUCLEAR REGULATORY COMMISSION

REGIONIV

611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011-8064

APR 1 4 1993

Docket Nos. 50-498 50-499 License Nos. NPF-76 NPF-80 FA 93-66

Houston Lighting & Power Company ATTN: Donald P. Hall, Group Vice President, Nuclear P.O. Box 1700 Houston, Texas 77251

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NO. 50-498/93-12; 50-499/93-12

This refers to the special inspection conducted by Mr. J. I. Tapia of this office between February 13 and March 18, 1993. The inspection included a review of activities authorized for your South Texas Project, Units 1 and 2, facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed report.

The inspection consisted of a review of the issues associated with undersized 120 volt vital ac electrical fuses. Within this area, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations of activities in progress.

Based on the results of this inspection, two apparent violations were identified and are being considered for escalated enforcement action in accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions" (Enforcement Policy), 10 CFR Part 2, Appendix C. Accordingly, no Notice of Violation is presently being issued for these inspection findings. Please be advised that the number and characterization of the apparent violations described in the enclosed inspection report may change as a result of further NRC review.

The first apparent violation involved a failure to include all design loads in the design of the circuits between the Solid State Protection System Actuation Cabinets and the corresponding 120 volt Vital AC Ungrounded Instrumentation and Control Power Distribution Panels as required by 10 CFR Part 50, Appendix B, Criterion III.

The second apparent violation involved operation of both units in violation of Technical Specification 3.3.2. Since initial facility operation, there was the potential for the actuation relays for safety injection, containment

9304200076 930414 PDR ADOCK 05000498 @ PDR

/JE14

Houston Lighting & Power Company -2-

isolation, main steam line isolation, turbine trip, main feedwater isolation, and auxiliary feedwater to become inoperable had a main steam line break event occurred.

An enforcement conference to discuss these apparent violations is scheduled for April 22, 1993, at 11 a.m. The decision to hold an enforcement conference does not mean that the NRC has determined that a violation has occurred or that enforcement action will be taken. The purposes of this conference are to discuss the apparent violations, their causes and safety significance; to provide you the opportunity to point out any errors in our inspection report; and to provide an opportunity for you to present your proposed corrective actions. In addition, this is an opportunity for you to provide any information concerning your perspectives on: (1) the severity of the violations, (2) the application of the factors that the NRC considers when it determines the amount of a civil penalty that may be assessed in accordance with Section VI.B.2 of the Enforcement Policy, and (3) any other application of the Enforcement Policy to this case, including the exercise of discretion in accordance with Section VII. You will be advised by separate correspondence of the results of our deliberations on this matter. No response regarding these apparent violations is required at this time. In accordance with 10 CFR Section 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosures will te placed in the NRC Public Document Room.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

A. Bill Beach, Director Division of Reactor Projects

Enclosure: Appendix - NRC Inspection Report 50-498/93-03; 50-499/93-03 w/attachment

cc w/enclosure: Houston Lighting & Power Company ATTN: William J. Jump, Manager Nuclear Licensing P.O. Box 289 Wadsworth, Texas 77483 Houston Lighting & Power Company -3-

City of Austin Electric Utility Department ATTN: J. C. Lanier/M. B. Lee P.O. Box 1088 Austin, Texas 78767

City Public Service Board ATTN: R. J. Costello/M. T. Hardt P.O. Box 1771 San Antonio, Texas 78296

Newman & Holtzinger, P. C. ATTN: Jack R. Newman, Esq. 1615 L Street, NW Washington, D.C. 20036

Central Power and Light Company ATTN: D. E. Ward/T. M. Puckett P.O. Box 2121 Corpus Christi, Texas 78403

INPO Records Center 1100 Circle 75 Parkway Atlanta, Georgia 30339-3064

Mr. Joseph M. Hendrie 50 Bellport Lane Bellport, New York 11713

Bureau of Radiation Control State of Texas 1101 West 49th Street Austin, Texas 78756

Judge, Matagorda County Matagorda County Courthouse 1700 Seventh Street Bay City, Texas 77414

Licensing Representative Houston Lighting & Power Company Suite 610 Three Metro Center Bethesda, Maryland 20814 Houston Lighting & Power Company -4-

Houston Lighting & Power Company ATTN: Rufus S. Scott, Associate General Counsel P.O. Box 61867 Houston, Texas 77208 Houston Lighting & Power Company

APR | 4 1993

bcc to DMB (IE14)

bcc distrib. by RIV: J. L. Milhoan DRP Lisa Shea, RM/ALF, MS: MNBB 4503 DRSS-FIPS Project Engineer (DRP/D) DRS G. F. Sanborn, EO W. L. Brown, RC A. B. Beach, D/DRP

Resident Inspector Section Chief (DRP/D) MIS System RIV File R. Bachmann, OGC, MS: 15-B-18 Section Chief (DRP/TSS) J. Lieberman, OE, MS: 7-H-5

RIV:SRI JITapia/ir TFStetka GESanborn JLbeberman ABBeer 4/2/93 4/2/93 4/2/93 4/2/93 4/2/93 4/2/93


-4-

Houston Lighting & Power Company -4-

bcc to DMB (IE14)

bcc distrib. by RIV: J. L. Milhoan DRP Lisa Shea, RM/ALF, MS: MNBB 4503 DRSS-F1PS Project Engineer (DRP/D) DRS G. F. Sanborn, EO W. L. Brown, RC A. B. Beach, D/DRP

Resident Inspector Section Chief (DRP/D) MIS System RIV File R. Bachmann, OGC, MS: 15-B-18 Section Chief (DRP/TSS) J. Lieberman, OE, MS: 7-H-5



APR | 4 1993