NRC FORM 591 PART 1 U.S. NUCLEAR REGULATORY COMMISSION (3-91) SAFETY INSPECTION 10 WR 2.201 Page 1 of C 1. LICENSEE Corps of Ensineers South Atlantic Div 2. REGIONAL OFFICE REGION II GH So Cabb Dr. U.S. NUCLEAR REGULATORY COMMISSION 101 MARIETTA STREET NW SUITE 2900 Marietto GA ATLANTA GA 30323 5. DATE OF INSPECTION 3. DOCKET NUMBER(S) 4. LICENSE NUMBER(S) 030-11078 LICENSEE The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The Inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The findings as a result of this inspection are as follows: Within the scope of this inspection, no violation's were observed The inspector also verified the steps you have taken to correct the violations identified during the last inspection. We have no further questions on those actions at this time. During this inspection certain of your activities, as described below or attached, were in violation of NRC requirements. This form is a NOTICE OF MOLATION, which is required to be posted in accordance with 10 CFR 19.11. was not properly posted to 10 CFR 20:203(b),(c),(d),(e) or 34.42. indicate the presence of a ___ of sealed sources were not performed at the proper frequencies. 10 CFR or License Condition Number Records of were not properly maintained. or License Condition Number ___ 10 CFR _____ D. Documents were not properly posted or otherwise made available. 10 CFR 19.11. Reports or notification of were not made in accordance with 10 OFR _____ or License Condition Number ____ 9304300027 920814 PDR ADOCK 03011078 PDR Thereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified in the Items checked above. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201. No further response will be submitted unless required by the NRC SIGNATURE - NRC INSPECTOR SIGNATURE - LICENSEE

NRC FORM 591 Part 1 (7-91)

(7-91)

SAFETY INSPECTION

10 CER 2.201	SAFETT INSPECTION	Page 2 of 2
1. LICENSEE CORPS OF End South Atlan 611 So Colo Marietta	Le De USA	
3. DOCKET NUMBER(S)	4. LICENSE NUMBER(S)	5. DATE OF INSPECTION
030-11078	10-16458-01	8 14 192
3. (Continued)		
G		
Н		

-71		
4. The violations listed below are not being cited because they were self-identified, and corrective action was or is being taken, and the remaining criteria in 10 CFR 2, App. C, to exercise discretion were satisfied.		
Dr Semiannual inventories exceeded 6 months		
on 2 or cassions between September 1990+		
September 1991 and September 1991 and June 1992		
for the Nickel 63, 15 m a source [License Condition 18]		
Ma Documents were not properly posted or		
otherwise made available as required by		
10 C FR 31.6.		
- C		
	#64	