

DUKE POWER COMPANY REGION
POWER BUILDING
ATLANTA, GEORGIA

422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

81 DEC 24 A10:42

WILLIAM O. PARKER, JR.
VICE PRESIDENT
STEAM PRODUCTION

December 17, 1981

TELEPHONE AREA 704
373-4083

Mr. J. P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303



Re: McGuire Nuclear Station Unit 1
Docket No. 50-369

Dear Mr. O'Reilly:

Please find attached Reportable Occurrence Report RO-369/81-184. This report concerns T.S.3.7.11, "All fire barrier penetrations (including cable penetration barriers, fire doors and fire dampers) in fire zone boundaries protecting safety-related areas, shall be functional". This incident was considered to be of no significance with respect to the health and safety of the public.

Note that the annual fire protection audit discovered another barrier breached on November 18, 1981. Since it was not possible to repair the barrier within seven days, in accordance with the action statement of T.S.3.7.11 a special report will be submitted pursuant to T.S.6.9.2.

Very truly yours,

William O. Parker, Jr.

PBN/jfw
Attachment

cc: Director
Office of Management and Program Analysis
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Records Center
Institute of Nuclear Power Operations
1820 Water Place
Atlanta, Georgia 30339

Mr. P. R. Bemis
Senior Resident Inspector-NRC
McGuire Nuclear Station

IE22
5
1/1

OFFICIAL COPY

8112290438 811117
PDR ADDCK 05000369
S PDR