



LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

December 21, 1981

G. D. McLENDON
Senior Vice President

W3K81-0457
Q-3-A35.07.30

Mr. John T. Collins, Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

SUBJECT: Waterford SES Unit 3
Docket No. 50-382
Third Interim Report
Significant Construction Deficiency No. 30
"Change Out of ASTM A193 S.S. Bolts on Motor Control
Center Bus Bars"



Reference: LP&L Letter W3K81-0400 to USNRC dated November 4, 1981

Dear Mr. Collins:

In the referenced letter, LP&L notified the NRC that the Final Report on Significant Construction Deficiency No. 30 would be delayed until December 15, 1981.

As of this date, a bolting material acquisition problem still exists. Based on this status, a final report will be submitted to the NRC by January 15, 1982.

If you have any questions, please let us know.

Very truly yours,

G. D. McLendon

GDMcL:LLB:ncd

- cc: 1) Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555
- 2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

8112310510 811221
PDR ADOCK 05000382
S PDR

IE 27
S/0