

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

[0] [7] [S] [C] [N] [E] [E] [3] [2] [0] [0] [-] [0] [0] [0] [0] [0] [-] [0] [0] [3] [4] [1] [1] [1] [1] [4] [5]

LICENSE CODE LICENSE NUMBER LICENSE TYPE CAT

CONT
[0] [1]
REPORT SOURCE [L] [5] [0] [5] [0] [0] [0] [2] [8] [7] [7] [1] [2] [0] [2] [8] [1] [3] [1] [2] [3] [1] [8] [1] [9]

DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
[0] [2] On December 2, 1981, while performing on-line testing, the Channel C Pump Power Monitor failed to send a trip signal. The RPS is required to have three channels operable. Channels A, B, and D were operable at the time of the Channel C failure; thus, the health and safety of the public were not affected by this incident.

[0] [3] Power Monitor failed to send a trip signal. The RPS is required to have three channels operable. Channels A, B, and D were operable at the time of the Channel C failure; thus, the health and safety of the public were not affected by this incident.

[0] [4] three channels operable. Channels A, B, and D were operable at the time of the Channel C failure; thus, the health and safety of the public were not affected by this incident.

[0] [5] affected by this incident.

[0] [6]

[0] [7]

[0] [8]

[0] [9]

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE

[1] [A] [11] [E] [12] [G] [13] [I] [N] [S] [T] [R] [U] [14] [Y] [15] [Z] [16]

LER/RD REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.

[17] [8] [1] [21] [0] [1] [6] [24] [0] [3] [27] [1] [20] [0]

ACTION TAKEN ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED APPROX FORM BUS PRIME COMP SUPPLIER COMPONENT MANUFACTURER

[A] [18] [Z] [19] [Z] [23] [Z] [21] [0] [0] [0] [0] [Y] [22] [N] [24] [L] [25] [B] [0] [4] [5] [26]

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
[1] [0] The apparent cause of this incident was a failed IC on the logic board of the Channel C Pump Power Monitor. The logic board was replaced, and the Channel C Pump Power Monitor was tested satisfactorily and returned to service.

[1] [1] Channel C Pump Power Monitor was tested satisfactorily and returned to service.

[1] [2]

[1] [3]

[1] [4]

FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION

[1] [5] [E] [28] [1] [0] [0] [29] NA [B] [31] Periodic on-line test

ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE

[1] [6] [Z] [32] [Z] [34] NA NA

PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION

[1] [7] [0] [0] [0] [37] [Z] [38] NA

PERSONNEL INJURIES NUMBER DESCRIPTION

[1] [8] [0] [0] [0] [40] NA

LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION

[1] [9] [Z] [42] NA

PUBLICITY ISSUED DESCRIPTION

[2] [0] [N] [44] NA

NRC USE ONLY

8201120335 811231
PDR ADOCK 05000287
S PDR

J. F. Kutzer

PHONE: (704) 373-7139