## "UPDATE REPORT - PREVIOUS REPORT DATE 12-18-81"

MRC FO	N. E. NUCLEAR REGULATORY COMMISSION
	LICENSEE EVENT REPORT EXHIBIT A
	CONTROL BLOCK:
01	C A D C P 1 30 101 -10 10 0 0 0 - 10 0 3 4 1 1 1 1 1 1 0 5 CAT S. 5
OI	MEPORT LL 16 0 5 0 0 0 0 2 7 5 0 0 9 2 7 8 1 8 0 0 1 1 1 1 8 2 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
0 2	Prior to start of fuel loading, Company Engineers, while in the process
0 3	of various design activities, discovered an error in a diagram used to
0 4	locate Vertical Seismic Floor Response (VSFR) spectra for use in plant
0 1	equipment and systems seismic design. The potential effect of this
0 6	error is that some designs may not be in compliance with Hosgri seismic
0 7	design criteria. Unit 2 is similarly affected. This report is submitted
0 8	in accordance with Technical Specification 6.9.1.12.i.
0 9	ZIZ TO BO A TO A TO A TO A TO A TO A TO A T
	17 LEA RO EVENT YEAR BEODET TOPE NO
	TAKEN ACTION SUTURE COMPLANT SHUTDOWN HOURS (27) ATTACHNIES T SORUSUS PRIME COMP COMPONENT MANUFACTURE OF THE COMPONENT OF THE COMPONENT MANUFACTURE OF THE COMPO
	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (2)
10	Diagram for Unit 2 was erroneously used for Unit 1 annulus area.
11	Incorrect diagram was used for Unit 1 VSFR spectra. Affected systems are
1 2	being reviewed and modifications, as necessary, performed. This LER is
13	updated by PGandE semi-monthly status reports to the Staff dated Dec. 24,
[]I	1981 and Jan. 8, 1982, submitted as a requirement of Order CLI 81-30.
15	B 18 0 10 10 10 NA NA STATUS 30 DISCOVERY DESCRIPTION 32 LA 31 Engineer Observation
	LEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA LOCATION OF RELEASE 36
1)	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION DO  NA  NA
, •:	PERSONNEL INJURIES 13 NUMBER DESCRIPTION (1) NA
, .	LOSS OF ON DAMAGE TO FACILITY (4) TYPE DESCAPTION NA
2 .	NAC USE ONLY
2 0	R. M. BACIARELLI (415)-541-6515
	NAME OF PREPARER PHONE
	8201190326 820111 PDR ADDCK 0820111