## LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1   I   Z   I   S   1   2   0   0   -   0   0   0   0   0   0   3   4   1   1   1   1   4   57   CAT 58   5
CON'T    O   1   SOURCE   L   O   O   O   O   O   O   O   O   O
During a routine inspection of the Aux. Building supply fans, discharge
[0]3 damper OFCV-AV03A on the OC Fan, was found failed open with the Fan off;
[0]4 This leaves the Aircraft Fire Protection System for the Aux. Building
[0] [Air Supply Intake inoperable. This is a violation of Tech. Spec. Sec-]
[0]6 [tion 3.17.2.1. No previous occurrences of this type Were found.
07
0 8 L 7 8 9 SYSTEM CAUSE CAUSE COMP. VALVE
CODE SUBCODE S
CODE
ACTION FUTURE ON PLANT SHUTDOWN HOURS 22 ATTACHMENT SUBMITTED FORM SUB. PRIME COMP. COMPONENT MANUFACTURER  A 18 Z 19 Z 20 Z 21 0 0 0 0 0 N 23 N 24 A 25 M 3 2 2 26  CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
[1] Upon investigation, it was found that the air operated relay valve,
[1] [ which controls instrument air to the damper, was frozen in its bore. ]
The relay was replaced, and the damper was successfully tested for
proper operation. No further corrective action is necessary.
7 8 9
FACILITY STATUS SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32  1 5 E 28 0 9 9 29 NA A 44 45 46 OPERATOR OBSERVATION 32
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35  NA LOCATION OF RELEASE 36  NA N
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39  NA  NA
PERSONNEL INJURIES NUMBER DESCRIPTION (41)
1 8 0 0 0 40 NA  7 8 2 SS OF OR DAMAGE TO FACILITY 43  TYPE DESCRIPTION  NA  8202020470 820127  PDR ADOCK 05000295
TYPE DESCRIPTION (43)  1 9 Z 42 NA
PUBLICITY ISSUED DESCRIPTION 45 NA
7 8 9 10  NAME OF PREPARER Fred Stahmer  PHONE 312-746-2084 Ext 353 9