## LICENSEE EVENT REPORT

	CONTROL BLOCK:
0 1	FIL T PS 3 2 0 0 - 0 0 0 0 0 0 0 3 4 1 1 1 1 1 4 57 CAT 38 5
GON'T	SOURCE 10 6 0 5 0 0 0 2 5 0 0 0 1 0 3 8 2 3 0 1 2 6 8 2 9
0 2	While repairs were being made to a penetration fire barrier, a fire watch
03	patrol failed to inspect the inoperable zone for three consecutive hours
0 4	(7AM to 10AM) as required by TS 3.14.4.a. Prior to this time and
0 5	immediately following, the inspections were performed properly. A similar
0 6	occurrence was reported as LER No. 250-81-0'4.
0 7	
7 5	SYSTEM CAUSE CAUSE COMP VALVE
0 9	A B 1 A 2 F 13 Z Z Z Z Z Z Z Z Z Z Z Z Z Z Z Z Z Z
	17 REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 32
	ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT SUBMITTED FORM SUB. PRIME COMP MANUFACTURER SUBMITTED FORM SUB. SUPPLIER MANUFACTURER LH 18 Z 19 Z 20 Z 21 O O O O O N 23 V 24 Z 25 Z 9 9 9 9 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
10	The break in surveillance of the inoperable barrier was caused by a mis-
	understanding by contractor personnel that an agreement had been made for
1 2	plant security personnel to maintain the inspections during the holidays.
[1]3]	Contractor personnel were instructed on the importance of complying with
1 4	TS 3.14.4.a
1 5	FACILITY STATUS OTHER STATUS OF DISCOVERY DESCRIPTION (32)  [G (3)   O   O   O   O   O   NA   A   Operator observation
	ACTIVITY CONTENT  RELEASED OF RELEASE  AMOUNT OF ACTIVITY (35)  NA  NA  NA  NA
7 3	3 3ERSONIEL EXPOSURES DESCRIPTION (39)
7 3	PERSONNEL NUCLIES NUMBER DESCRIPTION 41
1 3	0 0 0 40 NA
1 9	Coss of or Damage to Facility 43 Type Description  Z 42 NA
20	PUBLICITY ISSUED DESCRIPTION 45  NRC USE ONLY IN (44) NA
7 8	NAME OF PREPARER P.L. Pace PHONE (305) 552-3654